Map ID
Direction
Distance
Elevation   Site

MAP FINDINGS

EDR ID Number
Database(s)   EPA ID Number

I71	**MANHOLE 62303**		**NY Spills**	**S104651693**
ESE	**W 8TH ST/SHEEPSHEAD BAY**			**N/A**
1/8-1/4	**BROOKLYN, NY**			
0.158 mi.				
835 ft.	**Site 1 of 6 in cluster I**			

Relative:	SPILLS:	
Higher	Name:	MANHOLE 62303
Actual:	Address:	W 8TH ST/SHEEPSHEAD BAY
1 ft.	City,State,Zip:	BROOKLYN, NY
	Spill Number/Closed Date:	0000381 / 2002-01-17
	Facility ID:	0000381
	Facility Type:	ER
	DER Facility ID:	97791
	Site ID:	111847
	DEC Region:	2
	Spill Cause:	Unknown
	Spill Class:	C4
	SWIS:	2401
	Spill Date:	2000-04-10
	Investigator:	JHOCONNE
	Referred To:	Not reported
	Reported to Dept:	2000-04-10
	CID:	389
	Water Affected:	Not reported
	Spill Source:	Unknown
	Spill Notifier:	Other
	Cleanup Ceased:	Not reported
	Cleanup Meets Std:	False
	Last Inspection:	Not reported
	Recommended Penalty:	False
	UST Trust:	False
	Remediation Phase:	0
	Date Entered In Computer:	2000-04-10
	Spill Record Last Update:	2002-01-23
	Spiller Name:	Not reported
	Spiller Company:	UNK
	Spiller Address:	UNKNOWN
	Spiller Company:	999
	Contact Name:	CALLER
	DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis #130830 Notes: 4-10-00 1005hrs 1qt unknown oil on 100gal of water in manhole 62303. No other oil filled equipment in hole. Discovered spill while attempting to pull cable for open main. One liquid sample taken. 4-10-00 2257hrs LSN 00-03469 <1ppm PCB 4-15-00 1345hrs Cleanup completed by double washing with slix. Liquid waste removed by tanker, solids by vactor."
	Remarks:	"caller reporting a spill in a manhole samples taken clean up pending lab results coned#130830 no callback req"
	All Materials:	
	Site ID:	111847
	Operable Unit ID:	822099
	Operable Unit:	01
	Material ID:	288630
	Material Code:	0066A
	Material Name:	unknown petroleum
	Case No.:	Not reported
	Material FA:	Petroleum
	Quantity:	1.00

MAP FINDINGS

Units: G
Recovered: .00
Oxygenate: Not reported